

Rail Coach Screw Kit – PBK266



ERICO has developed a cost-effective system for quickly and effectively removing a broken screw spike in a concrete rail tie. Spike breaks normally occur in the tie insert and under the tie plate, which traditionally requires an expensive and time-consuming removal process. The Coach Screw Kit includes the components needed to initiate the reaction, thereby simplifying and expediting the extraction process.

- Effectively removes broken screw spikes in concrete rail ties
- For use with commonly used concrete tie screw spikes
- Convenient kit includes ERICO CADWELD mold, handle clamp and control unit to initiate the reaction
- ERICO CADWELD PLUS Welding Material is required for the process

Part Number	PBK266
Welding Material	PB90PLUSF80, Sold Separately
Standard Packaging Quantity	1 pc
UPC	78285670335

Items not included in the kit that must be supplied by the customer include: (1) 1/2" I.D. black pipe nipple, 4" long and (1) 9/16" high-strength steel drill bit for steel, 6" long.

Included in this Kit

Part Number	Description	Quantity
PLUSCU	ERICO CADWELD PLUS Control Unit, Controller Box with Leads, 6' Cable, 0-130 °F Working Temperature	1
XLL160	ERICO CADWELD EXOLON Handle Clamp, C, E, Q, R Price Key	1

WARNING

Pentair products shall be installed and used only as indicated in Pentair's product instruction sheets and training materials. Instruction sheets are available at erico.pentair.com and from your Pentair customer service representative. Improper installation, misuse, misapplication or other failure to completely follow Pentair's instructions and warnings may cause product malfunction, property damage, serious bodily injury and death and/or void your warranty.

© 2017 Pentair. All rights reserved.

Pentair, CADDY, CADWELD, CRITEC, ERICO, ERIFLEX, ERITECH and LENTON are owned by Pentair or its global affiliates.

All other trademarks are the property of their respective owners. Pentair reserves the right to change specifications without prior notice.