

Product data sheet

Specifications



license, EcoStruxure Automation Expert, run time, standard application, perpetual, 5000 IO devices, 1 user

EALDVMP

! Discontinued - Service only

! To be discontinued on: Dec 31, 2026

! To be end-of-service on: Dec 31, 2026

Product availability: Non-Stock - Not normally stocked in distribution facility

Main

Range of Product	EcoStruxure Automation Expert
Product or Component Type	License
Format	Digital
Type of License	Standard application
Software Version	V24.1
User Language	English Chinese German French Italian Spanish Portuguese Turkish Japanese

Complementary

Variant	Runtime
License category	Perpetual
Software Function	Engineering and operation
Communication Port Protocol	Modbus TCP server Modbus TCP client Modbus RTU server Modbus RTU client Ethernet/IP scanner MQTT client Profibus DP Profient RT OPC UA server OPC UA client AS-Interface
Hosting option	On-premise
License size	Single (1 user) 5000 devices
System Requirements	2 GB RAM 1 GHz or higher clock frequency

Price is "List Price" and may be subject to a trade discount – check with your local distributor or retailer for actual price.

Disclaimer: This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications

Processor requirement	Intel Celeron Intel Core i3 Intel Core i5 Intel Core i7 Intel Xeon
Display Resolution	1280 x 1024 pixels

Ordering and shipping details

Category	US1PC1522555
Discount Schedule	PC15
GTIN	3606487393870
Returnability	No
Country of origin	US

Contractual warranty

Warranty (in months)	18
----------------------	----



Environmental Data

Schneider Electric aims to achieve Net Zero status by 2050 through supply chain partnerships, lower impact materials, and circularity via our ongoing “Use Better, Use Longer, Use Again” campaign to extend product lifetimes and recyclability.

[Environmental Data explained >](#)

[How we assess product sustainability >](#)

Use Longer

Lifetime extension	
Repair	No